

Firmware Revisions jr+

09/23/97

jr+

Versions 2.01 (9-19-97 & 9-22-97)

Revisions

Version 2.01 (9-19-97)

The following bugs were fixed:

1. Would pulse out-dial only, due to modem level programming issue.
2. Would not connect to Racal test modem in outbound alert call.

Version 2.01 (9-22-97)

Fixed the following bugs:

1. Default values of OFF in logging configuration page, no effect upon values logged. Entire module broke.
2. Removed O field (read only password) which was attempting to change field A password.
3. Removed pass-through to AUX port command on screen 4. Using on a jr+ without aux ports would lock up local VDT machine. Could unplug VDT and replug to VDT port and log back in.
4. Concurrent outdial and indial would result in ProTek going off-hook, wait for dial tone, and hang up when hearing inbound ring. Outgoing alert call will now abort if inbound call arrives during alert call sequence.