

## Firmware Bug

08/24/98

24 classic

All firmware versions with bug

If an alert call fails due to a busy line and a status call is made within the following 15-second window, then the status call will be completed but the previously active alert call sequence will not be reactivated.